



279328

SAMPLE FIELD SHEET *

Site Name: <u>LUSHER AVENUE</u>	County: <u>ELKHART</u>
IDEM/OLQ Sample #: <u>E2P61</u>	Sample ID: <u>DW 55</u>
Collection Date: <u>13/DEC/2006</u>	Time: <u>4:14</u> AM/PM <u>AM</u>

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40ML</u>	<u>GLASS</u>	<u>3</u>	<u>HCL</u>	<u>UOT</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

1520 Albany 465161
5749712909

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Chris Langer
Sample obtained from south side of house through a rain hose
Deviations from Sampling Plan: Water Purged for 15 minutes
Slight sulfur odor.

SAMPLE FIELD SHEET *

Site Name: <u>LUSHER AVENUE</u>	County: <u>ELKHART</u>
IDEM/OLQ Sample #: <u>E2P62</u>	Sample ID: <u>DW56</u>
Collection Date: <u>13 DEC 2006</u>	Time: <u>4:14</u> AM / <u>PM</u>

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☒ Duplicate of E2P61 ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40 ML</u>	<u>GLASS</u>	<u>3</u>	<u>HCL</u>	<u>UOI</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Same as E2P61

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Same as E2P61

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

Site Name: <u>LUSHER AVENUE</u>	County: <u>ELKHART</u>
IDEM/OLQ Sample #: <u>E2P64</u>	Sample ID: <u>DW57</u>
Collection Date: <u>13 DEC 2006</u>	Time: <u>5:25</u> AM <input checked="" type="radio"/> PM

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☒ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40 mL</u>	<u>GLASS</u>	<u>3</u>	<u>HCL</u>	<u>UOT</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Background Sample - 1309 Concord
Toad Swomela 574-522-4422

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

2 res.

Deviations from Sampling Plan: _____

MS/MSD

SAMPLE FIELD SHEET *

Site Name: <u>LUSHER AVENUE</u>	County: <u>ELKHART</u>
IDEM/OLQ Sample #: <u>E2P66</u>	Sample ID: <u>DW 58</u>
Collection Date: <u>13 / DEC / 2006</u>	Time: <u>4 : 46 AM</u> <u>PM</u>

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40 ML</u>	<u>GLASS</u>	<u>9</u>	<u>HCL</u>	<u>UOA</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Burger King 2943176
1440 S. Nappanee, Elkhart 465147

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Sample obtained from faucet within food prep. area.
8 Emp. at least

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

Site Name: <u>LUSHER AVENUE</u>	County: <u>ELKHART</u>
IDEM/OLQ Sample #: <u>E2P67</u>	Sample ID: <u>DW59</u>
Collection Date: <u>12 DEC 2006</u>	Time: <u>7:00 AM/PM</u>

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40 ML</u>	<u>GLASS</u>		<u>HCL</u>	<u>UOA</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Trip Blank IDEM Shadeland office
Air Lake

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: _____

Revision 09-11-00

Sampler Signature: _____

Date: 12 DEC 2006